
New Features

- ACS6000 and ACS300 control panels now support use of AD400 Wireless Locks and PIM400-485 units.
- Implemented functionality needed to pulse an Allegion AD400 Wireless Lock.
- Implemented support for AD400 Wireless Locks with keypads.
- Panels maintain the current state of their inputs and outputs through a controlled restart of the panel.
- Implemented new monitoring and reporting of magnetic tamper events for Allegion NDE Wireless Locks.

Improvements

- Added the ability to enable or disable network monitoring from the webCLI.
- Administrator username and passwords in webCLI no longer allow 'space', '&', or '#' characters.
- Added detail memory usage for Brivo apps in the panel dump file.

Fixes

- Fixed an issue causing panel logs to show 'failed to sync hardware clock' messages.