
This version of firmware is for use with the ACS6000 and ACS300 control panels only.

Improvements

- Panel reboot now suppresses door forced and other hardware related events as a result of the panel restart.
- The panel datafile is preserved after a firmware upgrade.
- Improvements to the firmware upgrade/downgrade process.

Fixes

- Fixed an issue that in some situations would cause a one to two second delayed credential response.
- Fixed an issue where existing credential data was purged from the panel and reloaded from the server unnecessarily.
- Fixed an issue where the ACS6000 control panel experienced connectivity issues when using the SOCKS5 protocol.
- Fixed an issue where the local panel database could be become confused requiring an update from the server, temporarily causing the panel to become unresponsive to user credentials.